

# VEHICLE INSPECTION REPORT

**C310543**

## CARTWRIGHT BOX

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |            |                 |      |
|-----------|-------------|------------|------------|-----------------|------|
| Reg. date | 01/01/2011  | Colour     | WHITE      | Brakes          | Drum |
| Year      | 2011        | VIN        | 110132     | Axle Combi      | Tri  |
| Mileage   | Not Showing | Body Style | Trailer    | Rear Suspension | Air  |
| Fuel Type |             | MOT Due    | 31/03/2026 | Rear Doors      | Barn |

BPW AXLES, RAISE & LOWER VALVE

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos





