

VEHICLE INSPECTION REPORT

ML66WMG

Ford Transit 350 L3 Diesel Rwd 2.0 TDCi 130ps Dropside

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	37987
		Cap Code	FOTR20331RDDTM2 4 L

Details

Location	Avonmouth	GVW	3500kg	CAP Clean	£7,750.00
Reg. date	19/01/2017	Colour	WHITE	CAP Average	£6,475.00
Year	2017	VIN	WF0DXXTTGDGK83208	CAP Below	£4,775.00
Mileage	190,777 Miles Not Warranted	Body Style	Dropside L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	08/12/2026	Gears	6

AD BLUE

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Radio/CD
- Drivers airbag
- USB/iPod interface
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Wing Front Arch Extension ns
Broken
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Fuel Flap
Missing
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Multiple Chips



9: Door nsf
Rusted
UpTo 5mm



10: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



11: Bumper Rear
Cracked
Over 25mm



12: Door osf
Chipped
Multiple Chips



13: Door osf
Chipped
Multiple Chips



14: Wing Front Arch Extension os
Missing
Replace



15: Wing osf
Chipped
Over 5mm



16: Carpets Front
Holed
Over 3mm



17: Seat Base Cover osf
Torn
Over 3mm



18: Seat Base Cover nsf
Soiled
Heavy



19: Centre Console Front
Scuffed
Over 25mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		